



能源管理体系认证证书

兹证明

江西瑞一韵承科技有限公司

统一社会信用代码：913610263520996307
注册/生产地址：江西省抚州市宜黄县工业园丰厚B区

建立和实施的能源管理体系符合标准：
GB/T 23331-2020/ISO 50001:2018 《能源管理体系 要求及使用指南》
RB/T 119-2015 《能源管理体系 机械制造企业认证要求》

通过认证范围如下：
铝合金轮毂的生产过程涉及的能源管理活动
(综合能耗、能耗核算边界及能源管理体系边界见证书附件)

认证证书编号：29523EN100103R0M
证书签发日期：2023年10月20日
证书有效期至：2026年10月19日
首次注册日期：2023年10月20日



本证书由奥邦检验认证集团有限公司颁发。自2024年10月20日起，获证组织必须定期接受监督审核并经审定合格取得《监督审核合格通知书》时，本证书方继续有效。本证书信息可在国家认证认可监督管理委员会官方网站（www.cnca.gov.cn）上查询，或登录我司网站（www.cnabic.com）进行查询。



奥邦检验认证集团有限公司

地址：江苏省南京市鼓楼区古平岗4号（210013）
电话：025-85307007，传真：025-85307007，邮箱：info@cnabic.com



能源管理体系认证证书

附件：综合能耗、能耗核算边界及能源管理体系边界

审核类型及审核时间	单位产品/产值综合能耗	能源管理体系边界
2022年7月-2023年6月	2022 年 7 月-2023 年 6 月（企业申明所提供的数据真实有效，本次审核仅针对企业提供的数据进行统计） 综合能耗:3226.5039 tce 单位产品综合能耗:856.5186 kgce/吨 单位产值综合能耗:178.3979 kgce/万元	位于江西省抚州市宜黄县工业园丰厚 B 区的江西瑞一韵承科技有限公司从事铝合金轮毂的生产过程涉及的能源管理活动。主要生产系统包括铝合金锭熔炼、铸造、X 射线探伤、切冒口、旋压、热处理(退火)、抛丸、机加工、动平衡、气密性检验、涂装前处理、涂装、包装入库等过程。辅助生产系统:供电系统、给排水系统、供气系统、环保工程、设备设施维护、仓储系统、空气压缩系统、内部转运系统等；附属生产系统:行政办公、员工宿舍、食堂、检验等。 核算时间:2022 年 7 月-2023 年 6 月 产品产量:铝合金轮毂:3767 吨。 工厂范围:办公场所及铸造车间、热处理车间、机加车间、涂装车间、包装车间、仓库、食堂等。



奥邦检验认证集团有限公司

地址：江苏省南京市鼓楼区古平岗4号（210013）
电话：025-85307007，传真：025-85307007，邮箱：info@cnabic.com



EnMS CERTIFICATE OF REGISTRATION

THE ENERGY MANAGEMENT SYSTEM OF

Jiangxi Rayone Wheels Technology Company Limited

Social Credit Code: 913610263520996307

Register/Production Address: Zone B, Yihuang Industrial District, Fuzhou City, Jiangxi, China

Has been assessed by AUBURN® and complying with:

GB/T 23331-2020/ISO 50001:2018"Energy management systems—Requirements with guidance for use"

RB/T 119-2015"Energy management systems—Certification requirements for machinery enterprise"

For the following activities:

Energy Management Activities Involved in the Production Process of Aluminum Alloy Wheels

Certificate No: 29523EN100103R0M

Date of Issue: 20/10/2023

Date of Expiry: 19/10/2026

Initial Certification: 20/10/2023



This certificate issued by Auburn Inspection & Certification Group Co., Ltd. Since 20/10/2024, the certificate shall be used in conjunction with the <surveillance audit conformity notification> issued by AUBURN after the certified organization undergoing regular surveillance audit, and that the representation of efficiency will be validated. For obtaining the validity of certificate, please visit <http://www.cnabic.com>, the certificate information is also available on the CNCA official website: <http://www.cnca.gov.cn>.



AUBURN INSPECTION & CERTIFICATION GROUP CO., LTD.

Add.: No.4, Gupinggang Rd., Gulou District, Nanjing, 210013, P.R.China

Tel: 025-85307007, Fax: 025-85307007, Email: info@cnabic.com



EnMS CERTIFICATE OF REGISTRATION

Audit Type and Audit Time	Unit product/Comprehensive energy consumption of output value	Energy management system boundaries
July 2022-June 2023	July 2022-June 2023(The Company Declares That the Data Provided By the Company is True and Valid, and This Review Will Only Be Based on Statistics Provided By the Company) Comprehensive Energy Consumption: 3226.5039 tce Comprehensive Energy Consumption Per Unit of Product: 856.5186 kgce/ton Comprehensive Energy Consumption Per Unit of Output Value: 178.3979 kgce/10,000 yuan	Jiangxi Rayone Wheels Technology Company Limited, located in Zone B, Yihuang Industrial District, Fuzhou City, Jiangxi, China, is Engaged in Energy Management Activities Involved in the Production Process of Aluminum Alloy Wheels. The Main Production Systems Include Aluminum Alloy Ingot Smelting, Casting, X-ray Flaw Detection, Riser Cutting, Spinning, Heat Treatment (Annealing), Shot Blasting, Machining, Dynamic Balancing, Air Leakage Inspection, Pre-painting Treatment, Painting, Packaging and Warehousing Processes. Auxiliary Production Systems: Power Supply and Distribution Systems, Water Supply and Drainage Systems, Air Supply Systems, Environmental Protection Projects, Equipment and Facility Maintenance, Warehousing Systems, Air Compression Systems, Internal Transfer Systems, etc.; Affiliate Production Systems: Administrative Offices, Staff Dormitories, Canteens, inspections, etc. Accounting Time: July 2022-June 2023. Product Output: Aluminum Alloy Wheels: 3767 tons. Factory Scope: Office Space and Casting Workshop, Heat Treatment Workshop, Machining Workshop, Painting Workshop, Packaging Workshop, Warehouse, Canteen, etc.



AUBURN INSPECTION & CERTIFICATION GROUP CO., LTD.

Add.: No.4, Gupinggang Rd., Gulou District, Nanjing, 210013, P.R.China
Tel: 025-85307007, Fax: 025-85307007, Email: info@cnabic.com